



1184/1102P1

Standard Incandescent



1184/1100 IC Series

Incandescent Insulated Ceiling



1184/1103R

Lytecasting™ Non-IC Remodeler Ring

Complete Fixture consists of Frame-In Kit & Reflector Trim. Select each separately.

Reflector Trim		Frame-In Kit — See Individual Frame-In Kit Specification Sheets			
1184WH Gloss White		Incandescent			
		Frame-In Kit	Installation Type	Lamping	Height
		1102P1	Non-IC	75W PAR38 Outdoor Rated*	5 1/2"
		1103R	Non-IC Remodeler	75W PAR38 Outdoor Rated*	5 1/2"
		1100IC	IC	75W PAR38 Outdoor Rated*	7 5/16"
		1100AICM	AirSeal® IC	75W PAR38 Outdoor Rated*	7 5/16"
		1104ICX	AirSeal® IC	75W PAR38 Outdoor Rated*	7 1/4"

* For safe operation, you must use Sylvania or GE outdoor rated lamp.

Project: _____
 Location: _____
 Cat.No: _____
 Type: _____
 Lamps: _____ Qty: _____
 Notes: _____

1184 Lytecaster Reflector 6 3/4"

Lens Free Wet Location Trim

Features

1. **Reflectors:** Formed aluminum, .040 minimum thickness; gloss white and clear diffuse finish.
2. **Frame-In Kit:** (1102P1 standard frame shown). Other frames listed above and shown on the right. See Frame-In Kit specification sheets for more details.
3. **Gasket:** Flexible, high temperature silicone gasket ensure sealing of electrical components.

Labels

U.L. (Suitable for Wet Locations - Covered Ceiling Only), I.B.E.W.



© 2020 Signify Holding. All rights reserved. The information provided herein is subject to change, without notice. Signify does not give any representation or warranty as to the accuracy or completeness of the information included herein and shall not be liable for any action in reliance thereon. The information presented in this document is not intended as any commercial offer and does not form part of any quotation or contract, unless otherwise agreed by Signify.

Signify North America Corporation
200 Franklin Square Drive,
Somerset, NJ 08873
Telephone 855-486-2216

Signify Canada Ltd.
281 Hillmount Road,
Markham, ON, Canada L6C 2S3
Telephone 800-668-9008

All trademarks are owned by Signify Holding or their respective owners.