

Signify (China) Investment Co., Ltd.
Building no.9, Lane 888, Tianlin Road,
Minhang District, Shanghai 200233, China

Your letter
Your reference

Attn. Mr. Mao Xiaojun

Our reference

Author Mr. Lix Li
Direct line +86 21 60567611
Telefax +86 21 60567555
e-mail

Date 2022-08-24
number of pages : 1

Subject: Xitanium SR Bridge

To Whom It May Concern

We confirmed that the following products which are mentioned in the ENEC certifiante 31-101073 REV.1 and CB certificate NL-48058/M1 which was updated from DEKRA original ENEC certifiante 31-101073 and CB certificate NL-48058

Signify Product ID (12nc)	Product description	Brand
929001546406	Xitanium SR Bridge 9290 015 464	PHILIPS
929001546506	Xitanium SR Bridge 9290 015 465	PHILIPS
929003423706	Xitanium SR Bridge Built in	PHILIPS
929003423806	Xitanium SR Bridge Independent	PHILIPS

with followiing changes:

1. The hardware and firmwire for following SKUs do not change, only the reference standards listed in the certificate are updated to the latest version:
 - Xitanium SR Bridge 9290015464
 - Xitanium SR Bridge 9290015465
2. Add below 2 new SKUs into the current ENEC/CB certificate which have the exactly same hardware but with different firmware version:
 - **Xitanium SR Bridge Built-in** based on **Xitanium SR Bridge 9290015464**
 - **Xitanium SR Bridge Independent** based on **Xitanium SR Bridge 9290015465**

Yours faithfully,



Mr. Lix Li
Project Manager