

| Product Id | Model No.                                       | Classification |
|------------|---|----------------|
| PKPQUT1Z   | LBX40L835-(UNV120208240277)-(_OCCLBOCCHB)       | standard       |
| PRZWGRU8   | LBX40L835-(UNV120208240277)-(_OCCLBOCCHB)-FD    | standard       |
| PF72MNMX   | LBX40L835-(UNV120208240277)-(_OCCLBOCCHB)-UD    | standard       |
| P6NH6EEM   | LBX40L835-(UNV120208240277)-A)-(_OCCLBOCCHB)    | standard       |
| PC4JCJBB   | LBX40L835-(UNV120208240277)-M)-(_OCCLBOCCHB)    | standard       |
| PZ3RY9NC   | LBX40L835-(UNV120208240277)-N)-(_OCCLBOCCHB)    | standard       |
| PTNHPYME   | LBX40L835-(UNV120208240277)-W)-(_OCCLBOCCHB)    | standard       |
| PEADT7G2   | LBX40L835-347                                   | standard       |
| PYXFG2G2   | LBX40L835-347-A                                 | standard       |
| P1WR724A   | LBX40L835-347-FD                                | standard       |
| PRH35G27   | LBX40L835-347-M                                 | standard       |
| PAFF5QU3   | LBX40L835-347-N                                 | standard       |
| PMENG8UE   | LBX40L835-347-UD                                | standard       |
| P7T271QB   | LBX40L835-347-W                                 | standard       |
| PS3MH3AH   | LBX40L840-(UNV120208240277)-(_OCCLBOCCHB)       | standard       |
| P22AF43F   | LBX40L840-(UNV120208240277)-(_OCCLBOCCHB)-FD    | standard       |
| P4488GT3   | LBX40L840-(UNV120208240277)-(_OCCLBOCCHB)-UD    | standard       |
| P6K98VBG   | LBX40L840-(UNV120208240277)-A)-(_OCCLBOCCHB)    | standard       |
| PU9XYMBD   | LBX40L840-(UNV120208240277)-M)-(_OCCLBOCCHB)    | standard       |
| PTNWG31N   | LBX40L840-(UNV120208240277)-N)-(_OCCLBOCCHB)    | standard       |
| PDRYJG2G   | LBX40L840-(UNV120208240277)-W)-(_OCCLBOCCHB)    | standard       |
| PW4JR36N   | LBX40L840-347                                   | standard       |
| PYXDP9AK   | LBX40L840-347-A                                 | standard       |
| PF9P8SG1   | LBX40L840-347-FD                                | standard       |
| PBWHGYFZ   | LBX40L840-347-M                                 | standard       |
| PNY9VJBW   | LBX40L840-347-N                                 | standard       |
| PS1T3F4S   | LBX40L840-347-UD                                | standard       |
| PEYZETMM   | LBX40L840-347-W                                 | standard       |
| PF28FWSR   | LBX40L850-(UNV120208240277)-(_OCCLBOCCHB)       | standard       |
| PFGTW23D   | LBX40L850-(UNV120208240277)-(_OCCLBOCCHB)-FD    | standard       |
| P5EHPU5N   | LBX40L850-(UNV120208240277)-(_OCCLBOCCHB)-UD    | standard       |
| PZKGBDVT   | LBX40L850-(UNV120208240277)-A)-(_OCCLBOCCHB)    | standard       |
| PB5GJAKU   | LBX40L850-(UNV120208240277)-M)-(_OCCLBOCCHB)    | standard       |
| PEUKJVBY   | LBX40L850-(UNV120208240277)-N)-(_OCCLBOCCHB)    | standard       |
| P51QSNH9   | LBX40L850-(UNV120208240277)-W)-(_OCCLBOCCHB)    | standard       |
| PDGYR6FK   | LBX40L850-347                                   | standard       |
| PT65VR5V   | LBX40L850-347-A                                 | standard       |
| PXUEKQ67   | LBX40L850-347-FD                                | standard       |
| PJDGRRFF   | LBX40L850-347-M                                 | standard       |
| PBTYJHRR   | LBX40L850-347-N                                 | standard       |
| PDTVHQG4   | LBX40L850-347-UD                                | standard       |
| P186SRGZ   | LBX40L850-347-W                                 | standard       |
| PEWC7S3W   | LBX55L830-UNV-DA                                | standard       |
| PNDURJR5   | LBX55L835-(UNV120208240277347)-(_OCCLBOCCHB)    | standard       |
| PDMFMW8P   | LBX55L835-(UNV120208240277347)-(_OCCLBOCCHB)    | Premium        |
| PCCKFVBB   | LBX55L835-(UNV120208240277347)-(_OCCLBOCCHB)-FD | standard       |
| P1W3QVJ9   | LBX55L835-(UNV120208240277347)-(_OCCLBOCCHB)-FD | standard       |
| P4AKUSJG   | LBX55L835-(UNV120208240277347)-(_OCCLBOCCHB)-UD | standard       |
| PVZJ47F6   | LBX55L835-(UNV120208240277347)-(_OCCLBOCCHB)-UD | standard       |
| P8ZFW9AW   | LBX55L835-(UNV120208240277347)-A)-(_OCCLBOCCHB) | standard       |
| PP2FBK2P   | LBX55L835-(UNV120208240277347)-A)-(_OCCLBOCCHB) | Premium        |
| P38A7H75   | LBX55L835-(UNV120208240277347)-M)-(_OCCLBOCCHB) | standard       |
| PX3Y3V5E   | LBX55L835-(UNV120208240277347)-M)-(_OCCLBOCCHB) | Premium        |

| Product Id | Model No.  | Classification |
|------------|--|----------------|
| P8JGVM3M   | LBX55L835-(UNV120208240277347)-N-( _OCCLBOCCHB)    | standard       |
| PH39Q9WU   | LBX55L835-(UNV120208240277347)-N-( _OCCLBOCCHB)    | Premium        |
| P14TYW62   | LBX55L835-(UNV120208240277347)-W-( _OCCLBOCCHB)    | standard       |
| PVWGB8ND   | LBX55L835-(UNV120208240277347)-W-( _OCCLBOCCHB)    | Premium        |
| PW8GQCEQ   | LBX55L840-(UNV120208240277347)-( _OCCLBOCCHB)      | standard       |
| P2RT4B3U   | LBX55L840-(UNV120208240277347)-( _OCCLBOCCHB)      | Premium        |
| PQP4KQJK   | LBX55L840-(UNV120208240277347)-( _OCCLBOCCHB)-FD   | standard       |
| P19FK6BZ   | LBX55L840-(UNV120208240277347)-( _OCCLBOCCHB)-FD   | standard       |
| PDKJMEG6   | LBX55L840-(UNV120208240277347)-( _OCCLBOCCHB)-UD   | standard       |
| PKYGY956   | LBX55L840-(UNV120208240277347)-( _OCCLBOCCHB)-UD   | standard       |
| P1C8ER6H   | LBX55L840-(UNV120208240277347)-A-( _OCCLBOCCHB)    | standard       |
| PAPWPCDX   | LBX55L840-(UNV120208240277347)-A-( _OCCLBOCCHB)    | Premium        |
| P6X8NE4F   | LBX55L840-(UNV120208240277347)-M-( _OCCLBOCCHB)    | standard       |
| PB3PY5EB   | LBX55L840-(UNV120208240277347)-M-( _OCCLBOCCHB)    | Premium        |
| P93TF2QU   | LBX55L840-(UNV120208240277347)-N-( _OCCLBOCCHB)    | standard       |
| PZ8JXWK4   | LBX55L840-(UNV120208240277347)-N-( _OCCLBOCCHB)    | Premium        |
| P5PK6UAW   | LBX55L840-(UNV120208240277347)-W-( _OCCLBOCCHB)    | standard       |
| PCP9YZH4   | LBX55L840-(UNV120208240277347)-W-( _OCCLBOCCHB)    | Premium        |
| PUJNRZ65   | LBX55L850-(UNV120208240277347)-( _OCCLBOCCHB)      | standard       |
| P4P21E8Y   | LBX55L850-(UNV120208240277347)-( _OCCLBOCCHB)      | Premium        |
| P6HJWJGU   | LBX55L850-(UNV120208240277347)-( _OCCLBOCCHB)-FD   | standard       |
| PEA7QFGF   | LBX55L850-(UNV120208240277347)-( _OCCLBOCCHB)-FD   | standard       |
| P267KQDE   | LBX55L850-(UNV120208240277347)-( _OCCLBOCCHB)-UD   | standard       |
| P95X8F9J   | LBX55L850-(UNV120208240277347)-( _OCCLBOCCHB)-UD   | standard       |
| PS1EP2N6   | LBX55L850-(UNV120208240277347)-A-( _OCCLBOCCHB)    | standard       |
| PQ4N3GEG   | LBX55L850-(UNV120208240277347)-A-( _OCCLBOCCHB)    | Premium        |
| PYYJ75WM   | LBX55L850-(UNV120208240277347)-M-( _OCCLBOCCHB)    | standard       |
| PVYJUGG1   | LBX55L850-(UNV120208240277347)-M-( _OCCLBOCCHB)    | Premium        |
| PNV6R8MD   | LBX55L850-(UNV120208240277347)-N-( _OCCLBOCCHB)    | standard       |
| PBUFNUZY   | LBX55L850-(UNV120208240277347)-N-( _OCCLBOCCHB)    | Premium        |
| PUHVSHAD   | LBX55L850-(UNV120208240277347)-W-( _OCCLBOCCHB)    | standard       |
| PEGP5JFM   | LBX55L850-(UNV120208240277347)-W-( _OCCLBOCCHB)    | Premium        |
| PSNVD6SB   | LBX70L835-(UNV120208240277)-( _OCCLBOCCHBEMLED)    | standard       |
| PGPCX1WT   | LBX70L835-(UNV120208240277)-( _OCCLBOCCHBEMLED)    | Premium        |
| PTGC7T9G   | LBX70L835-(UNV120208240277)-( _OCCLBOCCHBEMLED)-FD | standard       |
| PQRZZ53W   | LBX70L835-(UNV120208240277)-( _OCCLBOCCHBEMLED)-FD | standard       |
| PV9ZQVGP   | LBX70L835-(UNV120208240277)-( _OCCLBOCCHBEMLED)-UD | standard       |
| PCNRHUWZ   | LBX70L835-(UNV120208240277)-( _OCCLBOCCHBEMLED)-UD | standard       |
| PKA5S3A7   | LBX70L835-(UNV120208240277)-A-( _OCCLBOCCHBEMLED)  | standard       |
| P6TXV5W9   | LBX70L835-(UNV120208240277)-A-( _OCCLBOCCHBEMLED)  | Premium        |
| PTV6TN2G   | LBX70L835-(UNV120208240277)-M-( _OCCLBOCCHBEMLED)  | standard       |
| P6Q34FU3   | LBX70L835-(UNV120208240277)-M-( _OCCLBOCCHBEMLED)  | Premium        |
| PKY38DK4   | LBX70L835-(UNV120208240277)-N-( _OCCLBOCCHBEMLED)  | standard       |
| PHFYXSYA   | LBX70L835-(UNV120208240277)-N-( _OCCLBOCCHBEMLED)  | Premium        |
| PP4TQN79   | LBX70L835-(UNV120208240277)-W-( _OCCLBOCCHBEMLED)  | standard       |
| PHQAN82M   | LBX70L835-(UNV120208240277)-W-( _OCCLBOCCHBEMLED)  | Premium        |
| PH5CY4ZG   | LBX70L835-(UNV120208240277347)-( _OCCLBOCCHB)      | standard       |
| PM6Z58Y    | LBX70L835-(UNV120208240277347)-( _OCCLBOCCHB)      | Premium        |
| PN1XDSDA   | LBX70L835-(UNV120208240277347)-( _OCCLBOCCHB)-FD   | standard       |
| PS2CPXWP   | LBX70L835-(UNV120208240277347)-( _OCCLBOCCHB)-FD   | standard       |
| PXGQFGAK   | LBX70L835-(UNV120208240277347)-( _OCCLBOCCHB)-UD   | standard       |
| P7VDMFT3   | LBX70L835-(UNV120208240277347)-( _OCCLBOCCHB)-UD   | standard       |
| PM6RR6U7   | LBX70L835-(UNV120208240277347)-A-( _OCCLBOCCHB)    | standard       |

| Product Id | Model No.  | Classification |
|------------|--|----------------|
| PGSRC8ED   | LBX70L835-(UNV120208240277347)-A-( _OCCLBOCCHB)    | Premium        |
| PGMBQC8J   | LBX70L835-(UNV120208240277347)-M-( _OCCLBOCCHB)    | standard       |
| P14UNUSV   | LBX70L835-(UNV120208240277347)-M-( _OCCLBOCCHB)    | Premium        |
| PZ45UB97   | LBX70L835-(UNV120208240277347)-N-( _OCCLBOCCHB)    | standard       |
| PGN552MX   | LBX70L835-(UNV120208240277347)-N-( _OCCLBOCCHB)    | Premium        |
| P8E4XF42   | LBX70L835-(UNV120208240277347)-W-( _OCCLBOCCHB)    | standard       |
| P4XVAHSA   | LBX70L835-(UNV120208240277347)-W-( _OCCLBOCCHB)    | Premium        |
| PWDHE7Y7   | LBX70L840-(UNV120208240277)-( _OCCLBOCCHBEMLED)    | standard       |
| PQXC324K   | LBX70L840-(UNV120208240277)-( _OCCLBOCCHBEMLED)    | Premium        |
| P9WG7EKF   | LBX70L840-(UNV120208240277)-( _OCCLBOCCHBEMLED)-FD | standard       |
| PDJW75EV   | LBX70L840-(UNV120208240277)-( _OCCLBOCCHBEMLED)-FD | standard       |
| PPVYPF27   | LBX70L840-(UNV120208240277)-( _OCCLBOCCHBEMLED)-UD | standard       |
| PYWKG6JM   | LBX70L840-(UNV120208240277)-( _OCCLBOCCHBEMLED)-UD | standard       |
| PPUXEANP   | LBX70L840-(UNV120208240277)-A-( _OCCLBOCCHBEMLED)  | standard       |
| PEE7T2CU   | LBX70L840-(UNV120208240277)-A-( _OCCLBOCCHBEMLED)  | Premium        |
| P1X411EV   | LBX70L840-(UNV120208240277)-M-( _OCCLBOCCHBEMLED)  | standard       |
| P1VY5R3P   | LBX70L840-(UNV120208240277)-M-( _OCCLBOCCHBEMLED)  | Premium        |
| PH3KEKM1   | LBX70L840-(UNV120208240277)-N-( _OCCLBOCCHBEMLED)  | standard       |
| P794ESE9   | LBX70L840-(UNV120208240277)-N-( _OCCLBOCCHBEMLED)  | Premium        |
| PGXW7Y2U   | LBX70L840-(UNV120208240277)-W-( _OCCLBOCCHBEMLED)  | standard       |
| P885B9Y1   | LBX70L840-(UNV120208240277)-W-( _OCCLBOCCHBEMLED)  | Premium        |
| PUEHAB4H   | LBX70L840-(UNV120208240277347)-( _OCCLBOCCHB)      | standard       |
| PMJVSCW9   | LBX70L840-(UNV120208240277347)-( _OCCLBOCCHB)      | Premium        |
| PUWA7MUH   | LBX70L840-(UNV120208240277347)-( _OCCLBOCCHB)-FD   | standard       |
| PKGRZQM2   | LBX70L840-(UNV120208240277347)-( _OCCLBOCCHB)-FD   | standard       |
| P9PGPEVF   | LBX70L840-(UNV120208240277347)-( _OCCLBOCCHB)-UD   | standard       |
| PJCD2AAE   | LBX70L840-(UNV120208240277347)-( _OCCLBOCCHB)-UD   | standard       |
| P3PH6QGF   | LBX70L840-(UNV120208240277347)-A-( _OCCLBOCCHB)    | standard       |
| P9MYD9ZU   | LBX70L840-(UNV120208240277347)-A-( _OCCLBOCCHB)    | Premium        |
| P7AHMW4G   | LBX70L840-(UNV120208240277347)-M-( _OCCLBOCCHB)    | standard       |
| PXABWBA3   | LBX70L840-(UNV120208240277347)-M-( _OCCLBOCCHB)    | Premium        |
| PSVZZKMY   | LBX70L840-(UNV120208240277347)-N-( _OCCLBOCCHB)    | standard       |
| P8BJ24FN   | LBX70L840-(UNV120208240277347)-N-( _OCCLBOCCHB)    | Premium        |
| PGJH83SH   | LBX70L840-(UNV120208240277347)-W-( _OCCLBOCCHB)    | standard       |
| PBNVX7D4   | LBX70L840-(UNV120208240277347)-W-( _OCCLBOCCHB)    | Premium        |
| PJQTTFP2   | LBX70L850-(UNV120208240277)-( _OCCLBOCCHBEMLED)    | standard       |
| PN923YSX   | LBX70L850-(UNV120208240277)-( _OCCLBOCCHBEMLED)    | Premium        |
| P2AEWXCX   | LBX70L850-(UNV120208240277)-( _OCCLBOCCHBEMLED)-FD | standard       |
| P6FGQP8Q   | LBX70L850-(UNV120208240277)-( _OCCLBOCCHBEMLED)-FD | standard       |
| PW2VZ1BS   | LBX70L850-(UNV120208240277)-( _OCCLBOCCHBEMLED)-UD | standard       |
| PH2M4Z66   | LBX70L850-(UNV120208240277)-( _OCCLBOCCHBEMLED)-UD | standard       |
| P4SZ5JSV   | LBX70L850-(UNV120208240277)-A-( _OCCLBOCCHBEMLED)  | standard       |
| P5G43TWM   | LBX70L850-(UNV120208240277)-A-( _OCCLBOCCHBEMLED)  | Premium        |
| PDA7XZ7X   | LBX70L850-(UNV120208240277)-M-( _OCCLBOCCHBEMLED)  | standard       |
| P9HXXNHT   | LBX70L850-(UNV120208240277)-M-( _OCCLBOCCHBEMLED)  | Premium        |
| PV13QRQZ   | LBX70L850-(UNV120208240277)-N-( _OCCLBOCCHBEMLED)  | standard       |
| PQGPAKXA   | LBX70L850-(UNV120208240277)-N-( _OCCLBOCCHBEMLED)  | Premium        |
| PVVCXJBW   | LBX70L850-(UNV120208240277)-W-( _OCCLBOCCHBEMLED)  | standard       |
| P4CTNQDU   | LBX70L850-(UNV120208240277)-W-( _OCCLBOCCHBEMLED)  | Premium        |
| PTYJCR1R   | LBX70L850-(UNV120208240277347)-( _OCCLBOCCHB)      | standard       |
| PW358UNS   | LBX70L850-(UNV120208240277347)-( _OCCLBOCCHB)      | Premium        |
| P73Y77GX   | LBX70L850-(UNV120208240277347)-( _OCCLBOCCHB)-FD   | standard       |
| PPTQ11UH   | LBX70L850-(UNV120208240277347)-( _OCCLBOCCHB)-FD   | standard       |

| Product Id | Model No.                                       | Classification |
|------------|---|----------------|
| P9H98E9A   | LBX70L850-(UNV120208240277347)-(_OCCLBOCCHB)-UD | standard       |
| PMCUHZB9   | LBX70L850-(UNV120208240277347)-(_OCCLBOCCHB)-UD | standard       |
| PB2KJW2J   | LBX70L850-(UNV120208240277347)-A-( _OCCLBOCCHB) | standard       |
| PYHUETFU   | LBX70L850-(UNV120208240277347)-A-( _OCCLBOCCHB) | Premium        |
| P7XG9Q9W   | LBX70L850-(UNV120208240277347)-M-( _OCCLBOCCHB) | standard       |
| P56X1CRC   | LBX70L850-(UNV120208240277347)-M-( _OCCLBOCCHB) | Premium        |
| PMYVHFGX   | LBX70L850-(UNV120208240277347)-N-( _OCCLBOCCHB) | standard       |
| PZG22FU2   | LBX70L850-(UNV120208240277347)-N-( _OCCLBOCCHB) | Premium        |
| P7ETUHCV   | LBX70L850-(UNV120208240277347)-W-( _OCCLBOCCHB) | standard       |
| P8NXVTC5   | LBX70L850-(UNV120208240277347)-W-( _OCCLBOCCHB) | Premium        |
| PMDYEBWR   | LBX80L835-(UNV120208240277)-(_EMLED)            | standard       |
| PVR81FVJ   | LBX80L835-(UNV120208240277)-(_EMLED)            | Premium        |
| P78358FA   | LBX80L835-(UNV120208240277)-(_EMLED)-FD         | standard       |
| P7TMJBVR   | LBX80L835-(UNV120208240277)-(_EMLED)-FD         | standard       |
| PFS7SHBY   | LBX80L835-(UNV120208240277)-(_EMLED)-UD         | standard       |
| P49T1HE4   | LBX80L835-(UNV120208240277)-(_EMLED)-UD         | standard       |
| PVP183ND   | LBX80L835-(UNV120208240277)-A-( _EMLED)         | standard       |
| PEU5VDVT   | LBX80L835-(UNV120208240277)-A-( _EMLED)         | Premium        |
| PX21PZZW   | LBX80L835-(UNV120208240277)-M-( _EMLED)         | standard       |
| P6BVCFZY   | LBX80L835-(UNV120208240277)-M-( _EMLED)         | Premium        |
| PTT5PNEQ   | LBX80L835-(UNV120208240277)-N-( _EMLED)         | standard       |
| PCPTXXTV   | LBX80L835-(UNV120208240277)-N-( _EMLED)         | Premium        |
| PZ3PGAX2   | LBX80L835-(UNV120208240277)-W-( _EMLED)         | standard       |
| PD11TSZW   | LBX80L835-(UNV120208240277)-W-( _EMLED)         | Premium        |
| PXVBAB62   | LBX80L835-(UNV120208240277347)-(_OCCLBOCCHB)    | standard       |
| PG3U3SZQ   | LBX80L835-(UNV120208240277347)-(_OCCLBOCCHB)    | Premium        |
| PZ8FJHMK   | LBX80L835-(UNV120208240277347)-(_OCCLBOCCHB)-FD | standard       |
| PNUWQJ7N   | LBX80L835-(UNV120208240277347)-(_OCCLBOCCHB)-FD | standard       |
| PFBRJSQX   | LBX80L835-(UNV120208240277347)-(_OCCLBOCCHB)-UD | standard       |
| P7KA87UE   | LBX80L835-(UNV120208240277347)-(_OCCLBOCCHB)-UD | standard       |
| P8CD56J6   | LBX80L835-(UNV120208240277347)-A-( _OCCLBOCCHB) | standard       |
| PDJ8J74Q   | LBX80L835-(UNV120208240277347)-A-( _OCCLBOCCHB) | Premium        |
| PWN12ZM9   | LBX80L835-(UNV120208240277347)-M-( _OCCLBOCCHB) | standard       |
| PWQ1ZQA5   | LBX80L835-(UNV120208240277347)-M-( _OCCLBOCCHB) | Premium        |
| PGZPY344   | LBX80L835-(UNV120208240277347)-N-( _OCCLBOCCHB) | standard       |
| PYF9499D   | LBX80L835-(UNV120208240277347)-N-( _OCCLBOCCHB) | Premium        |
| PVYDE3ET   | LBX80L835-(UNV120208240277347)-W-( _OCCLBOCCHB) | standard       |
| P8ZFK5B7   | LBX80L835-(UNV120208240277347)-W-( _OCCLBOCCHB) | Premium        |
| P278THEZ   | LBX80L840-(UNV120208240277)-(_EMLED)            | standard       |
| P5K1DUPS   | LBX80L840-(UNV120208240277)-(_EMLED)            | Premium        |
| PT8EFX6D   | LBX80L840-(UNV120208240277)-(_EMLED)-FD         | standard       |
| PTMJC2V8   | LBX80L840-(UNV120208240277)-(_EMLED)-FD         | standard       |
| PVRSTAM9   | LBX80L840-(UNV120208240277)-(_EMLED)-UD         | standard       |
| PETMV1EV   | LBX80L840-(UNV120208240277)-(_EMLED)-UD         | standard       |
| PNCVZV3P   | LBX80L840-(UNV120208240277)-A-( _EMLED)         | standard       |
| P2KWC8CN   | LBX80L840-(UNV120208240277)-A-( _EMLED)         | Premium        |
| PQ91CEN5   | LBX80L840-(UNV120208240277)-M-( _EMLED)         | standard       |
| P39J2UKJ   | LBX80L840-(UNV120208240277)-M-( _EMLED)         | Premium        |
| PQ2HSGJZ   | LBX80L840-(UNV120208240277)-N-( _EMLED)         | standard       |
| P8AEX4JT   | LBX80L840-(UNV120208240277)-N-( _EMLED)         | Premium        |
| P1HTE819   | LBX80L840-(UNV120208240277)-W-( _EMLED)         | standard       |
| PEUXB98J   | LBX80L840-(UNV120208240277)-W-( _EMLED)         | Premium        |
| PGXW34UQ   | LBX80L840-(UNV120208240277347)-(_OCCLBOCCHB)    | standard       |

| Product Id | Model No.                                       | Classification |
|------------|---|----------------|
| PTANDGYS   | LBX80L840-(UNV120208240277347)-(_OCCLBOCCHB)    | Premium        |
| P5P4XMMC   | LBX80L840-(UNV120208240277347)-(_OCCLBOCCHB)-FD | standard       |
| P2KBMS6D   | LBX80L840-(UNV120208240277347)-(_OCCLBOCCHB)-FD | standard       |
| P9QCTTJE   | LBX80L840-(UNV120208240277347)-(_OCCLBOCCHB)-UD | standard       |
| PUTS66BD   | LBX80L840-(UNV120208240277347)-(_OCCLBOCCHB)-UD | standard       |
| PYHB4BKW   | LBX80L840-(UNV120208240277347)-A-(_OCCLBOCCHB)  | standard       |
| PGQHREEX   | LBX80L840-(UNV120208240277347)-A-(_OCCLBOCCHB)  | Premium        |
| P4CUWCPG   | LBX80L840-(UNV120208240277347)-M-(_OCCLBOCCHB)  | standard       |
| P4XBU8BC   | LBX80L840-(UNV120208240277347)-M-(_OCCLBOCCHB)  | Premium        |
| PNDKK4RV   | LBX80L840-(UNV120208240277347)-N-(_OCCLBOCCHB)  | standard       |
| P1HHZ6Y7   | LBX80L840-(UNV120208240277347)-N-(_OCCLBOCCHB)  | Premium        |
| PPQ458W2   | LBX80L840-(UNV120208240277347)-W-(_OCCLBOCCHB)  | standard       |
| PBCM8U5G   | LBX80L840-(UNV120208240277347)-W-(_OCCLBOCCHB)  | Premium        |
| P4QXRR5T   | LBX80L850-(UNV120208240277)-(_EMLED)            | standard       |
| P2ZHVKQ3   | LBX80L850-(UNV120208240277)-(_EMLED)            | Premium        |
| PPV92J3B   | LBX80L850-(UNV120208240277)-(_EMLED)-FD         | standard       |
| PW96ET5Z   | LBX80L850-(UNV120208240277)-(_EMLED)-FD         | standard       |
| PMJBH86W   | LBX80L850-(UNV120208240277)-(_EMLED)-UD         | standard       |
| PY1X8AZY   | LBX80L850-(UNV120208240277)-(_EMLED)-UD         | standard       |
| PK3GY3VK   | LBX80L850-(UNV120208240277)-A-(_EMLED)          | standard       |
| PXDRFK4Q   | LBX80L850-(UNV120208240277)-A-(_EMLED)          | Premium        |
| P4G8CY4A   | LBX80L850-(UNV120208240277)-M-(_EMLED)          | standard       |
| PZDKB6YG   | LBX80L850-(UNV120208240277)-M-(_EMLED)          | Premium        |
| PX7FWTY8   | LBX80L850-(UNV120208240277)-N-(_EMLED)          | standard       |
| P5QFRDDT   | LBX80L850-(UNV120208240277)-N-(_EMLED)          | Premium        |
| PUKUVXUC   | LBX80L850-(UNV120208240277)-W-(_EMLED)          | standard       |
| PUQT7UJB   | LBX80L850-(UNV120208240277)-W-(_EMLED)          | Premium        |
| PF3XA1ET   | LBX80L850-(UNV120208240277347)-(_OCCLBOCCHB)    | standard       |
| PK2V8W41   | LBX80L850-(UNV120208240277347)-(_OCCLBOCCHB)    | Premium        |
| PWQ2YJHV   | LBX80L850-(UNV120208240277347)-(_OCCLBOCCHB)-FD | standard       |
| PQJBM8P3   | LBX80L850-(UNV120208240277347)-(_OCCLBOCCHB)-FD | standard       |
| PNAZV8AY   | LBX80L850-(UNV120208240277347)-(_OCCLBOCCHB)-UD | standard       |
| PTAENJWP   | LBX80L850-(UNV120208240277347)-(_OCCLBOCCHB)-UD | standard       |
| PN6WQGY1   | LBX80L850-(UNV120208240277347)-A-(_OCCLBOCCHB)  | standard       |
| PGP8HPKS   | LBX80L850-(UNV120208240277347)-A-(_OCCLBOCCHB)  | Premium        |
| PSYDFBHY   | LBX80L850-(UNV120208240277347)-M-(_OCCLBOCCHB)  | standard       |
| P1UV5FFY   | LBX80L850-(UNV120208240277347)-M-(_OCCLBOCCHB)  | Premium        |
| PQKB8ZSA   | LBX80L850-(UNV120208240277347)-N-(_OCCLBOCCHB)  | standard       |
| P1CBUQGF   | LBX80L850-(UNV120208240277347)-N-(_OCCLBOCCHB)  | Premium        |
| PSP8JRPF   | LBX80L850-(UNV120208240277347)-W-(_OCCLBOCCHB)  | standard       |
| PS7F3EZX   | LBX80L850-(UNV120208240277347)-W-(_OCCLBOCCHB)  | Premium        |
| PJ49YTP3   | LBX90L835-(UNV120208240277347)-(_EMLED)         | standard       |
| PW9XNJY5   | LBX90L835-(UNV120208240277347)-(_EMLED)         | standard       |
| P6AWTS2E   | LBX90L835-(UNV120208240277347)-(_EMLED)-FD      | standard       |
| PR1J2EMU   | LBX90L835-(UNV120208240277347)-(_EMLED)-FD      | standard       |
| P2YSHA78   | LBX90L835-(UNV120208240277347)-(_EMLED)-UD      | standard       |
| PKKX6S29   | LBX90L835-(UNV120208240277347)-(_EMLED)-UD      | standard       |
| P1XXJTY5   | LBX90L835-(UNV120208240277347)-(_OCCLBOCCHB)    | standard       |
| PK2CNM1U   | LBX90L835-(UNV120208240277347)-(_OCCLBOCCHB)    | Premium        |
| PSXF2JVG   | LBX90L835-(UNV120208240277347)-(_OCCLBOCCHB)-FD | standard       |
| PT7VK3K7   | LBX90L835-(UNV120208240277347)-(_OCCLBOCCHB)-FD | standard       |
| P4DST45T   | LBX90L835-(UNV120208240277347)-(_OCCLBOCCHB)-UD | standard       |
| PR1RG52M   | LBX90L835-(UNV120208240277347)-(_OCCLBOCCHB)-UD | standard       |

| Product Id | Model No.  | Classification |
|------------|--|----------------|
| PKRQG161   | LBX90L835-(UNV120208240277347)-A-( _EMLED)       | standard       |
| PQGNVMAK   | LBX90L835-(UNV120208240277347)-A-( _EMLED)       | standard       |
| P1SAQSGU   | LBX90L835-(UNV120208240277347)-A-( _OCCLBOCCHB)  | standard       |
| P7K8AEEU   | LBX90L835-(UNV120208240277347)-A-( _OCCLBOCCHB)  | Premium        |
| PFNP918Q   | LBX90L835-(UNV120208240277347)-M-( _EMLED)       | standard       |
| P8SJJ8BU   | LBX90L835-(UNV120208240277347)-M-( _EMLED)       | standard       |
| PNR1GG77   | LBX90L835-(UNV120208240277347)-M-( _OCCLBOCCHB)  | standard       |
| P9UG2BZ1   | LBX90L835-(UNV120208240277347)-M-( _OCCLBOCCHB)  | Premium        |
| PU91FCRQ   | LBX90L835-(UNV120208240277347)-N-( _EMLED)       | standard       |
| PRKZ8DWA   | LBX90L835-(UNV120208240277347)-N-( _EMLED)       | standard       |
| PGGC33E1   | LBX90L835-(UNV120208240277347)-N-( _OCCLBOCCHB)  | standard       |
| P7JQJPDV   | LBX90L835-(UNV120208240277347)-N-( _OCCLBOCCHB)  | Premium        |
| PFEM3NYX   | LBX90L835-(UNV120208240277347)-W-( _EMLED)       | standard       |
| P32VF7Q8   | LBX90L835-(UNV120208240277347)-W-( _EMLED)       | standard       |
| P1DTD6C7   | LBX90L835-(UNV120208240277347)-W-( _OCCLBOCCHB)  | standard       |
| PRM3YNX7   | LBX90L835-(UNV120208240277347)-W-( _OCCLBOCCHB)  | Premium        |
| P9Z9T83G   | LBX90L840-(UNV120208240277347)-( _EMLED)         | standard       |
| PQ69UX6H   | LBX90L840-(UNV120208240277347)-( _EMLED)         | standard       |
| PSJJQ2E9   | LBX90L840-(UNV120208240277347)-( _EMLED)-FD      | standard       |
| PXPE4B5R   | LBX90L840-(UNV120208240277347)-( _EMLED)-FD      | standard       |
| PFMF84YG   | LBX90L840-(UNV120208240277347)-( _EMLED)-UD      | standard       |
| PRPHRS1F   | LBX90L840-(UNV120208240277347)-( _EMLED)-UD      | standard       |
| PKPQ5JJ3   | LBX90L840-(UNV120208240277347)-( _OCCLBOCCHB)    | standard       |
| PQMB4JN3   | LBX90L840-(UNV120208240277347)-( _OCCLBOCCHB)    | Premium        |
| P6GCFNTG   | LBX90L840-(UNV120208240277347)-( _OCCLBOCCHB)-FD | standard       |
| PGRUG37N   | LBX90L840-(UNV120208240277347)-( _OCCLBOCCHB)-FD | standard       |
| PTCK4MUY   | LBX90L840-(UNV120208240277347)-( _OCCLBOCCHB)-UD | standard       |
| P6M1BXSC   | LBX90L840-(UNV120208240277347)-( _OCCLBOCCHB)-UD | standard       |
| P6CNVTYV   | LBX90L840-(UNV120208240277347)-A-( _EMLED)       | standard       |
| PE4JUW9W   | LBX90L840-(UNV120208240277347)-A-( _EMLED)       | standard       |
| P2MFCQZZ   | LBX90L840-(UNV120208240277347)-A-( _OCCLBOCCHB)  | standard       |
| PAMP3CP9   | LBX90L840-(UNV120208240277347)-A-( _OCCLBOCCHB)  | Premium        |
| PKVYZTPW   | LBX90L840-(UNV120208240277347)-M-( _EMLED)       | standard       |
| P23TFTCG   | LBX90L840-(UNV120208240277347)-M-( _EMLED)       | standard       |
| PCGHPW2X   | LBX90L840-(UNV120208240277347)-M-( _OCCLBOCCHB)  | standard       |
| PCMN2WZX   | LBX90L840-(UNV120208240277347)-M-( _OCCLBOCCHB)  | Premium        |
| PJ6DSDTQ   | LBX90L840-(UNV120208240277347)-N-( _EMLED)       | standard       |
| P1YN74RG   | LBX90L840-(UNV120208240277347)-N-( _EMLED)       | standard       |
| PMCJ1WHD   | LBX90L840-(UNV120208240277347)-N-( _OCCLBOCCHB)  | standard       |
| PHCGMJ6B   | LBX90L840-(UNV120208240277347)-N-( _OCCLBOCCHB)  | Premium        |
| P56D83TH   | LBX90L840-(UNV120208240277347)-W-( _EMLED)       | standard       |
| PAX18GV9   | LBX90L840-(UNV120208240277347)-W-( _EMLED)       | standard       |
| PTWD4FC3   | LBX90L840-(UNV120208240277347)-W-( _OCCLBOCCHB)  | standard       |
| PGWNSNUN   | LBX90L840-(UNV120208240277347)-W-( _OCCLBOCCHB)  | Premium        |
| P6DG768T   | LBX90L850-(UNV120208240277347)-( _EMLED)         | standard       |
| PK2WWJDJ   | LBX90L850-(UNV120208240277347)-( _EMLED)         | Premium        |
| PRBVKFJ9   | LBX90L850-(UNV120208240277347)-( _EMLED)-FD      | standard       |
| P89GYFGR   | LBX90L850-(UNV120208240277347)-( _EMLED)-FD      | standard       |
| PSQ96FSG   | LBX90L850-(UNV120208240277347)-( _EMLED)-UD      | standard       |
| P4TURQHB   | LBX90L850-(UNV120208240277347)-( _EMLED)-UD      | standard       |
| PKER3JQ1   | LBX90L850-(UNV120208240277347)-( _OCCLBOCCHB)    | standard       |
| PXAAK5FQ   | LBX90L850-(UNV120208240277347)-( _OCCLBOCCHB)    | Premium        |
| PJAY8RWQ   | LBX90L850-(UNV120208240277347)-( _OCCLBOCCHB)-FD | standard       |

11/6/2019

Information as of this date. Please check the DLC QPL for confirmation ([www.designlights.org/QPL](http://www.designlights.org/QPL)).

| Product Id | Model No.   | Classification |
|------------|---|----------------|
| PEYBFTV2   | LBX90L850-(UNV120208240277347)-(_OCCLBOCCHB)-FD       | standard       |
| P8C41JWQ   | LBX90L850-(UNV120208240277347)-(_OCCLBOCCHB)-UD       | standard       |
| P3HJ14GG   | LBX90L850-(UNV120208240277347)-(_OCCLBOCCHB)-UD       | standard       |
| P5TXWHJA   | LBX90L850-(UNV120208240277347)-A-(_EMLED)             | standard       |
| PWZ54RW9   | LBX90L850-(UNV120208240277347)-A-(_EMLED)             | Premium        |
| PGD7AWWW   | LBX90L850-(UNV120208240277347)-A-(_OCCLBOCCHB)        | standard       |
| PJVEFZUS   | LBX90L850-(UNV120208240277347)-A-(_OCCLBOCCHB)        | Premium        |
| P91DXU2F   | LBX90L850-(UNV120208240277347)-M-(_EMLED)             | standard       |
| PYRJWZCC   | LBX90L850-(UNV120208240277347)-M-(_EMLED)             | standard       |
| PB7N1YUU   | LBX90L850-(UNV120208240277347)-M-(_OCCLBOCCHB)        | standard       |
| P5DNGRWM   | LBX90L850-(UNV120208240277347)-M-(_OCCLBOCCHB)        | Premium        |
| PNFF662R   | LBX90L850-(UNV120208240277347)-N-(_EMLED)             | standard       |
| P1KJUEA9   | LBX90L850-(UNV120208240277347)-N-(_EMLED)             | standard       |
| PX3GAF1C   | LBX90L850-(UNV120208240277347)-N-(_OCCLBOCCHB)        | standard       |
| PHJVQMHV   | LBX90L850-(UNV120208240277347)-N-(_OCCLBOCCHB)        | Premium        |
| P6184949   | LBX90L850-(UNV120208240277347)-W-(_EMLED)             | standard       |
| P5DRWQEJ   | LBX90L850-(UNV120208240277347)-W-(_EMLED)             | standard       |
| PMZD14J4   | LBX90L850-(UNV120208240277347)-W-(_OCCLBOCCHB)        | standard       |
| PPK1AMAP   | LBX90L850-(UNV120208240277347)-W-(_OCCLBOCCHB)        | Premium        |
| PM4QJHGA   | LBX110L5830-UNV-DA                                    | standard       |
| PF1JCZVH   | LBX110L835-(UNV120208240277347)-(_OCCLBOCCHBEMLED)    | standard       |
| PA8C97SK   | LBX110L835-(UNV120208240277347)-(_OCCLBOCCHBEMLED)-FD | standard       |
| PPFDVJGQ   | LBX110L835-(UNV120208240277347)-(_OCCLBOCCHBEMLED)-UD | standard       |
| PRX2BPMS   | LBX110L835-(UNV120208240277347)-A-(_OCCLBOCCHBEMLED)  | standard       |
| PKZJ4JDA   | LBX110L835-(UNV120208240277347)-M-(_OCCLBOCCHBEMLED)  | standard       |
| PJZY6A2G   | LBX110L835-(UNV120208240277347)-N-(_OCCLBOCCHBEMLED)  | standard       |
| PPYC59T8   | LBX110L835-(UNV120208240277347)-W-(_OCCLBOCCHBEMLED)  | standard       |
| PJWMH2Y2   | LBX110L840-(UNV120208240277347)-(_OCCLBOCCHBEMLED)    | standard       |
| P966G6W8   | LBX110L840-(UNV120208240277347)-(_OCCLBOCCHBEMLED)-FD | standard       |
| PAQ3XXZM   | LBX110L840-(UNV120208240277347)-(_OCCLBOCCHBEMLED)-UD | standard       |
| PZA5BBXF   | LBX110L840-(UNV120208240277347)-A-(_OCCLBOCCHBEMLED)  | standard       |
| PC74WQZ7   | LBX110L840-(UNV120208240277347)-M-(_OCCLBOCCHBEMLED)  | standard       |
| PCGGZCK3   | LBX110L840-(UNV120208240277347)-N-(_OCCLBOCCHBEMLED)  | standard       |
| PTFHA6WP   | LBX110L840-(UNV120208240277347)-W-(_OCCLBOCCHBEMLED)  | standard       |
| PBHNT2P2   | LBX110L850-(UNV120208240277347)-(_OCCLBOCCHBEMLED)    | standard       |
| PKV2VM84   | LBX110L850-(UNV120208240277347)-(_OCCLBOCCHBEMLED)-FD | standard       |
| P3TUKJQU   | LBX110L850-(UNV120208240277347)-(_OCCLBOCCHBEMLED)-UD | standard       |
| PJN4A9QY   | LBX110L850-(UNV120208240277347)-A-(_OCCLBOCCHBEMLED)  | standard       |
| PFMXAXXC   | LBX110L850-(UNV120208240277347)-M-(_OCCLBOCCHBEMLED)  | standard       |
| PRDH5CPN   | LBX110L850-(UNV120208240277347)-N-(_OCCLBOCCHBEMLED)  | standard       |
| PTB92AWT   | LBX110L850-(UNV120208240277347)-W-(_OCCLBOCCHBEMLED)  | standard       |
| PE6SNKR1   | LBX140L835-(UNV120208240277)-(_OCCLBOCCHBEMLED)       | standard       |
| PF5JG359   | LBX140L835-(UNV120208240277)-(_OCCLBOCCHBEMLED)-FD    | standard       |
| PNZMMH9A   | LBX140L835-(UNV120208240277)-(_OCCLBOCCHBEMLED)-UD    | standard       |
| PMF6BEXM   | LBX140L835-(UNV120208240277)-A-(_OCCLBOCCHBEMLED)     | standard       |
| PEUBEUSX   | LBX140L835-(UNV120208240277)-M-(_OCCLBOCCHBEMLED)     | standard       |
| PDR62NM1   | LBX140L835-(UNV120208240277)-N-(_OCCLBOCCHBEMLED)     | standard       |
| P3DBPT2Z   | LBX140L835-(UNV120208240277)-W-(_OCCLBOCCHBEMLED)     | standard       |
| PUHFJ95U   | LBX140L835-(UNV120208240277347)-(_OCCLBOCCHB)         | standard       |
| PD3USFNU   | LBX140L835-(UNV120208240277347)-(_OCCLBOCCHB)-FD      | standard       |
| PEX1AUEW   | LBX140L835-(UNV120208240277347)-(_OCCLBOCCHB)-UD      | standard       |
| PRHGZXZZ   | LBX140L835-(UNV120208240277347)-A-(_OCCLBOCCHB)       | standard       |
| P2Q5C8YP   | LBX140L835-(UNV120208240277347)-M-(_OCCLBOCCHB)       | standard       |

| Product Id | Model No.   | Classification |
|------------|---|----------------|
| PGP212HF   | LBX140L835-(UNV120208240277347)-N-( _OCCLBOCCHB)    | standard       |
| P4D1PHTG   | LBX140L835-(UNV120208240277347)-W-( _OCCLBOCCHB)    | standard       |
| P5U9DRGP   | LBX140L840-(UNV120208240277)-( _OCCLBOCCHBEMLED)    | standard       |
| P7A5SGCX   | LBX140L840-(UNV120208240277)-( _OCCLBOCCHBEMLED)-FD | standard       |
| PHGWRUZ8   | LBX140L840-(UNV120208240277)-( _OCCLBOCCHBEMLED)-UD | standard       |
| PNHZSP1P   | LBX140L840-(UNV120208240277)-A-( _OCCLBOCCHBEMLED)  | standard       |
| PX2C2JZW   | LBX140L840-(UNV120208240277)-M-( _OCCLBOCCHBEMLED)  | standard       |
| P2VNQJ2T   | LBX140L840-(UNV120208240277)-N-( _OCCLBOCCHBEMLED)  | standard       |
| PSM87RGV   | LBX140L840-(UNV120208240277)-W-( _OCCLBOCCHBEMLED)  | standard       |
| PHSNX66N   | LBX140L840-(UNV120208240277347)-( _OCCLBOCCHB)      | standard       |
| PJNVV9H6   | LBX140L840-(UNV120208240277347)-( _OCCLBOCCHB)-FD   | standard       |
| PZTPJ28V   | LBX140L840-(UNV120208240277347)-( _OCCLBOCCHB)-UD   | standard       |
| PJ3GZ71C   | LBX140L840-(UNV120208240277347)-A-( _OCCLBOCCHB)    | standard       |
| PK9ZGZQ3   | LBX140L840-(UNV120208240277347)-M-( _OCCLBOCCHB)    | standard       |
| P2Q82YA3   | LBX140L840-(UNV120208240277347)-N-( _OCCLBOCCHB)    | standard       |
| P513KSXW   | LBX140L840-(UNV120208240277347)-W-( _OCCLBOCCHB)    | standard       |
| PN8WF7GB   | LBX140L850-(UNV120208240277)-( _OCCLBOCCHBEMLED)    | standard       |
| PP4N3EBH   | LBX140L850-(UNV120208240277)-( _OCCLBOCCHBEMLED)-FD | standard       |
| PF4DG11Z   | LBX140L850-(UNV120208240277)-( _OCCLBOCCHBEMLED)-UD | standard       |
| PB4GCD97   | LBX140L850-(UNV120208240277)-A-( _OCCLBOCCHBEMLED)  | standard       |
| P71155WX   | LBX140L850-(UNV120208240277)-M-( _OCCLBOCCHBEMLED)  | standard       |
| PAT8UX58   | LBX140L850-(UNV120208240277)-N-( _OCCLBOCCHBEMLED)  | standard       |
| P2D9VEQP   | LBX140L850-(UNV120208240277)-W-( _OCCLBOCCHBEMLED)  | standard       |
| PWS4ZTKP   | LBX140L850-(UNV120208240277347)-( _OCCLBOCCHB)      | standard       |
| PFQRU7UV   | LBX140L850-(UNV120208240277347)-( _OCCLBOCCHB)-FD   | standard       |
| P1636Q99   | LBX140L850-(UNV120208240277347)-( _OCCLBOCCHB)-UD   | standard       |
| PKDRJE82   | LBX140L850-(UNV120208240277347)-A-( _OCCLBOCCHB)    | standard       |
| PNX75AEQ   | LBX140L850-(UNV120208240277347)-M-( _OCCLBOCCHB)    | standard       |
| PHBF993P   | LBX140L850-(UNV120208240277347)-N-( _OCCLBOCCHB)    | standard       |
| PUSK19XU   | LBX140L850-(UNV120208240277347)-W-( _OCCLBOCCHB)    | standard       |
| PC6JJAS3   | LBX180L835-(UNV120208240277347)-( _EMLED)           | standard       |
| PUBDBC3G   | LBX180L835-(UNV120208240277347)-( _EMLED)-FD        | standard       |
| P1U1NYV9   | LBX180L835-(UNV120208240277347)-( _EMLED)-UD        | standard       |
| PY1YC87W   | LBX180L835-(UNV120208240277347)-( _OCCLBOCCHB)      | standard       |
| PGTP8B1Z   | LBX180L835-(UNV120208240277347)-( _OCCLBOCCHB)-FD   | standard       |
| PDTAEBKM   | LBX180L835-(UNV120208240277347)-( _OCCLBOCCHB)-UD   | standard       |
| PDJE4HYH   | LBX180L835-(UNV120208240277347)-A-( _EMLED)         | standard       |
| PKX3APEN   | LBX180L835-(UNV120208240277347)-A-( _OCCLBOCCHB)    | standard       |
| PA32PTWV   | LBX180L835-(UNV120208240277347)-M-( _EMLED)         | standard       |
| PY2RU6A2   | LBX180L835-(UNV120208240277347)-M-( _OCCLBOCCHB)    | standard       |
| PD98B9HU   | LBX180L835-(UNV120208240277347)-N-( _EMLED)         | standard       |
| P4XV33Y9   | LBX180L835-(UNV120208240277347)-N-( _OCCLBOCCHB)    | standard       |
| PHRP41QY   | LBX180L835-(UNV120208240277347)-W-( _EMLED)         | standard       |
| P6WYD68P   | LBX180L835-(UNV120208240277347)-W-( _OCCLBOCCHB)    | standard       |
| PH6JUS8R   | LBX180L840-(UNV120208240277347)-( _EMLED)           | standard       |
| PDWAAHKD   | LBX180L840-(UNV120208240277347)-( _EMLED)-FD        | standard       |
| PQTCEU8B   | LBX180L840-(UNV120208240277347)-( _EMLED)-UD        | standard       |
| PZXUUDE4   | LBX180L840-(UNV120208240277347)-( _OCCLBOCCHB)      | standard       |
| PYMCXS83   | LBX180L840-(UNV120208240277347)-( _OCCLBOCCHB)-FD   | standard       |
| PXWKDUPK   | LBX180L840-(UNV120208240277347)-( _OCCLBOCCHB)-UD   | standard       |
| PZ9GUX6F   | LBX180L840-(UNV120208240277347)-A-( _EMLED)         | standard       |
| PQK3XXSP   | LBX180L840-(UNV120208240277347)-A-( _OCCLBOCCHB)    | standard       |
| PUXYQWWC   | LBX180L840-(UNV120208240277347)-M-( _EMLED)         | standard       |

11/6/2019

Information as of this date. Please check the DLC QPL for confirmation ([www.designlights.org/QPL](http://www.designlights.org/QPL)).

| Product Id | Model No.   | Classification |
|------------|---|----------------|
| P13G2UMJ   | LBX180L840-(UNV120208240277347)-M-( _OCCLBOCCHB)  | standard       |
| PWTZDUEA   | LBX180L840-(UNV120208240277347)-N-( _EMLED)       | standard       |
| PQ5QKBDA   | LBX180L840-(UNV120208240277347)-N-( _OCCLBOCCHB)  | standard       |
| PG7YA78V   | LBX180L840-(UNV120208240277347)-W-( _EMLED)       | standard       |
| PJAB5AWZ   | LBX180L840-(UNV120208240277347)-W-( _OCCLBOCCHB)  | standard       |
| PERD9R9V   | LBX180L850-(UNV120208240277347)-( _EMLED)         | standard       |
| PA7VRH38   | LBX180L850-(UNV120208240277347)-( _EMLED)-FD      | standard       |
| PG6ZGSQ1   | LBX180L850-(UNV120208240277347)-( _EMLED)-UD      | standard       |
| PZPH5N1A   | LBX180L850-(UNV120208240277347)-( _OCCLBOCCHB)    | standard       |
| P6UVUCEU   | LBX180L850-(UNV120208240277347)-( _OCCLBOCCHB)-FD | standard       |
| PV9ZJEER   | LBX180L850-(UNV120208240277347)-( _OCCLBOCCHB)-UD | standard       |
| PAZTU6UF   | LBX180L850-(UNV120208240277347)-A-( _EMLED)       | standard       |
| PKYAYYRA   | LBX180L850-(UNV120208240277347)-A-( _OCCLBOCCHB)  | standard       |
| P8T6MP68   | LBX180L850-(UNV120208240277347)-M-( _EMLED)       | standard       |
| PUSU6J4E   | LBX180L850-(UNV120208240277347)-M-( _OCCLBOCCHB)  | standard       |
| P482ZZ7X   | LBX180L850-(UNV120208240277347)-N-( _EMLED)       | standard       |
| P8WUU956   | LBX180L850-(UNV120208240277347)-N-( _OCCLBOCCHB)  | standard       |
| PS4WDZZG   | LBX180L850-(UNV120208240277347)-W-( _EMLED)       | standard       |
| PDVJXCAD   | LBX180L850-(UNV120208240277347)-W-( _OCCLBOCCHB)  | standard       |